



7,412 Hours

2,442 Landings



Highlights

- Batch 3.4 Avionic Upgrade
- ADS-B Out Compliance
- Equipped FANS 1/A+
- SwiftBroadband Internet
- Fresh 240 Month Inspection
- Cabin Refurbished in 2021
- New Bespoke Carpet for Installation before Delivery
- Exceptional interior

Airframe

TOTAL TIME SINCE NEW	7,412 Hours (as of July 28, 2022)
TOTAL LANDINGS SINCE NEW	2,442 Landings
CERTIFICATION DATE	September 1999
INSERVICE DATE	September 2000
HOME BASE	Johannesburg, South Africa
PROGRAM COVERAGE	Smart Parts Plus
MAINTENANCE TRACKING	CAMP
CERTIFICATION	

Engines	Left	Right
DESCRIPTION	Rolls Royce BR700	710A2-20
SERIAL NUMBER(S)	12149	12156
TOTAL HOURS SINCE NEW	7,410 Hours	7,270 Hours
TOTAL CYCLES SINCE NEW	2,422 Cycles	2,387 Cycles
PROGRAM COVERAGE	Rolls-Royce Corpora	ateCare

APU

DESCRIPTION	Honeywell RE220
SERIAL NUMBER	P-120
APU TOTAL TIME SINCE NEW	6,368 Hours
PROGRAM COVERAGE	Honeywell MSP Gold

Connectivity

HIGH SPEED INTERNET	SwiftBroadband WiFi w/ SATCOM Direct Router
PHONE SYSTEM	Iridium Phone System

Entertainment

DISPLAY	Three (3) High Definition Screens
CABIN MANAGEMENT SYSTEM	Flight Display Systems DO Capsule with on-board media server



Avionics

Type of unit	Qty	Description
EFIS (ELECTRONIC FLIGHT INSTRUMENT SYSTEM)	Six- Tube	Honeywell DU-870
FMS (FLIGHT MANAGEMENT SYSTEM)	Dual	Honeywell NZ-2000
CDU (CENTRAL DISPLAY UNIT)	Triple	Honeywell CD-820
IRS (INERTIAL REFERENCE SYSTEM)	Triple	Honeywell IRS Unit
GPS (GLOBAL POSITIONING SYSTEM)	Dual	Honeywell GPS Unit
ADC (AIR DATA COMPUTER)	Triple	Honeywell AZ-840
NAV (NAVIGATION RADIO)	Dual	Honeywell RNZ-851
ADF (AUTOMATIC DIRECTION FINDER)	Dual	Honeywell AT-860
VHF COM (VERY HIGH FREQ. COMMUNICATIONS)	Triple	Honeywell RCZ-833 w/ 8.33 KHz Spacing
HF COM (HIGH FREQ. COMMUNICATIONS)	Dual	Rockwell Collins HF-9031A w/ SELCAL
WRADAR (WEATHER RADAR)	Single	Honeywell WC-880
RADAR ALT (RADAR ALTIMETER)	Dual	Collins ALT-4000
EGPWS (ENHANCED GROUND PROXIMITY WARNING SYSTEM)	Single	Honeywell Mark V Unit
TCAS (TRAFFIC COLLISION AVOIDANCE SYSTEM)	Single	Honeywell TCZ-910 TCAS II w/ Change 7:1
CVR (COCKPIT VOICE RECORDER)	Single	Honeywell SSCVR

Type of unit	Qty	Description
FDR (FLIGHT DATA RECORDER)	Single	Honeywell SSFDR
ELT (EMERGENCY LOCATOR TRANSMITTER)	Single	Artex 406 Hz
LSS (LIGHTING SENSOR SYSTEM)	Single	Honeywell LP-8502

Major inspection status

Inspection	Last Performed	Next Due
60 Month	August 2021	August 2025
120 Month	August 2021	August 2030
240 Month	August 2021	August 2030

Notable service bulletins

SB 700-23-015 - Airborne Data Link System
SB 700-31-030 Rev. 2 - Batch 3.4 Avionics
SB 700-34-014 Part (C) - RVSM
SB 700-34-053 Rev. 1 - FANS 1/A+
SB 700-34-062 Rev. 3 - ADS-B Out




Interior

NUMBER OF PASSENGERS	Twelve (12)
GALLEY LOCATION	Forward
FORWARD CABIN CONFIGURATION	Four (4) Place Double Club
MID CABIN CONFIGURATION	Two (2) Place Club Opposite Four (4) Place Conference Group
AFT CABIN CONFIGURATION	Two (2) Place Club Opposite Three (3) Place 9G Divan
LAVATORY LOCATION(S)	Forward Crew and Aft Executive
CREW REST	Yes
JUMPSEAT	Yes
LAST REFURBISHED DATE	Full Bombardier interior refit and upgrade in 2015. Followed by detailed interior refresh in 2021 including seat refurbishment, cabinetry and leather work as required. New carpet ready

Exterior

BASE PAINT COLOR(S)	Matterhorn White
SECONDARY COLOR(S)	Mercedes Brown
LAST PAINTED DATE	Painted by Bombardier in September 2015

Floorplan










































FOR YOUR WORLD