



2,915 Hours

1,422Landings



Highlights

- ARCS Complete and Ready to Close Immediately
- Engines Enrolled on Rolls-Royce
 Corporate Care Enhanced
- Enhanced Navigation
- Synthetic Vision System
- ACA lonizer Installation
- Windshield Blower Installation
- One Owner Since New
- Impeccably Maintained and Professionally Operated
- Never Chartered
- New Brakes in July 2025
- Sixteen Passenger Configuration



Airframe

| TOTAL TIME SINCE NEW | 2,915 Hours (as of November 2025) |
|--------------------------|-----------------------------------|
| TOTAL LANDINGS SINCE NEW | 1,422 Landings |
| ENTRY INTO SERVICE DATE | September 2010 |
| MAINTENANCE TRACKING | CMP |

| Engines | Left | Right |
|------------------------|-------------------|-------------------|
| DESCRIPTION | Rolls-Royce BR70 | 0-710C4-11 |
| SERIAL NUMBER(S) | 15663 | 15662 |
| TOTAL HOURS SINCE NEW | 2,915 Hours | 2,915 Hours |
| TOTAL CYCLES SINCE NEW | 1,422 Cycles | 1,422 Cycles |
| PROGRAM COVERAGE | Rolls-Royce Corpo | rateCare Enhanced |

Avionics

The Gulfstream G550 is equipped with an integrated, Honeywell PlaneView avionics suite

APU

| DESCRIPTION | Honeywell RE220 |
|--------------------------|-----------------|
| SERIAL NUMBER | P-612 |
| APU TOTAL TIME SINCE NEW | 2,430 Hours |

Connectivity

| INTERNET ATG-400 | 00 |
|------------------|----|
|------------------|----|

Notable Aircraft Service Changes

| Aircraft Service Change | Description |
|-------------------------|-----------------------------------|
| ASC049 | Lightning Sensor System |
| ASC053 | Arinc Direct DLK Service Provider |
| ASCO61 | Synthetic Vision System (SVS) |
| ASC084 | Enhanced Navigation (FANS 1A) |
| ASC097 | DLK Recording |
| ASC912C | PlaneView Master Operating System |





Interior

| NUMBER OF PASSENGERS | Sixteen (16) |
|--------------------------------|--|
| GALLEY LOCATION | Aft |
| FORWARD CABIN CONFIGURATION | Four (4) Place Club and Two (2) Forward Facing Seats |
| MID CABIN CONFIGURATION | Four (4) Place Conference Group opposite a Credenza |
| AFT CABIN CONFIGURATION | Two (2) Place Club opposite Four (4) Place Divan |
| LAVATORY LOCATION(S) | Forward and Aft |
| LAST REFURBISHED DATE | Original |


Exterior

| BASE PAINT COLOR(S) | Matterhorn White |
|-------------------------|------------------|
| STRIPE COLOR(S) | Blue |
| LAST REFURBISHMENT DATE | Original |

Major inspection status

| Inspection | Last Performed | Next Due |
|-----------------|----------------|----------------|
| 1C 12 Month | August 2025 | August 2026 |
| 2C 24 Month | August 2024 | August 2026 |
| 4C 48 Month | July 2022 | July 2026 |
| 6C 72 Month | September 2022 | September 2028 |
| 8C 96 Month | September 2018 | September 2026 |
| 12C 144 Month | August 2022 | July 2034 |
| 16C 192 Month | - | September 2026 |

Floorplan

































































registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.





Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos,



FOR YOUR WORLD