



2000 BOMBARDIER GLOBAL EXPRESS S/N 9023



2000 BOMBARDIER GLOBAL EXPRESS S/N 9023

HIGHLIGHTS

BATCH 3 AVIONIC UPGRADE



ADS-B OUT COMPLIANCE



EQUIPPED FANS 1/A+



SWIFTBROADBAND INTERNET



FRESH 240 MONTH INSPECTION

AIRFRAME

TOTAL TIME SINCE NEW	7,227 Hours (as of September 24, 2021)
TOTAL LANDINGS SINCE NEW	2,351 Landings
CERTIFICATION DATE	September 1999
INSERVICE DATE	September 2000
HOME BASE	Johannesburg, South Africa
PROGRAM COVERAGE	Smart Parts Plus
MAINTENANCE TRACKING	CAMP
CERTIFICATION	SACAA Part 135



ENGINES

	Left Engine	Right Engine
DESCRIPTION	Rolls Royce BR700-710A2-20	
SERIAL NUMBER(S)	12149	12156
TOTAL HOURS SINCE NEW	7,223 Hours	7,084 Hours
TOTAL CYCLES SINCE NEW	2,330 Cycles	2,296 Cycles
PROGRAM COVERAGE	Rolls-Royce CorporateCare	



APU

DESCRIPTION	Honeywell RE220
SERIAL NUMBER	P-120
APU TOTAL TIME SINCE NEW	6,099 Hours
PROGRAM COVERAGE	Honeywell MSP Gold

2000 BOMBARDIER GLOBAL EXPRESS S/N 9023

AVIONICS

Type of Unit	Quantity	Description
EFIS (Electronic Flight Instrument System)	Six-Tube	Honeywell DU-870
FMS (Flight Management System)	Dual	Honeywell NZ-2000
CDU (Central Display Unit)	Triple	Honeywell CD-820
IRS (Inertial Reference System)	Triple	Honeywell IRS Unit
GPS (Global Positioning System)	Dual	Honeywell GPS Unit
ADC (Air Data Computer)	Triple	Honeywell AZ-840
NAV (Navigation Radio)	Dual	Honeywell RNZ-851
ADF (Automatic Direction Finder)	Dual	Honeywell AT-860
VHF COM (Very High Freq. Communications)	Triple	Honeywell RCZ-833 w/ 8.33 KHz Spacing
HF COM (High Freq. Communications)	Dual	Rockwell Collins HF-9031A w/ SELCAL
WRADAR (Weather Radar)	Single	Honeywell WC-880
RADAR ALT (Radar Altimeter)	Dual	Collins ALT-4000
EGPWS (Enhanced Ground Proximity Warning System)	Single	Honeywell Mark V Unit
TCAS (Traffic Collision Avoidance System)	Single	Honeywell TCZ-910 TCAS II w/ Change 7.1
CVR (Cockpit Voice Recorder)	Single	Honeywell SSCVR
FDR (Flight Data Recorder)	Single	Honeywell SSFDR
ELT (Emergency Locator Transmitter)	Single	Artex 406 Hz
LSS (Lighting Sensor System)	Single	Honeywell LP-8502

NOTABLE SERVICE BULLETIN COMPLIANCE

SB 700-23-015 – Airborne Data Link System
 SB 700-31-030 Rev. 2 – Batch 3.4 Avionics
 SB 700-34-014 Part (C) – RVSM
 SB 700-34-053 Rev. 1 – FANS 1/A+
 SB 700-34-062 Rev. 3 – ADS-B Out



MAJOR INSPECTION STATUS

Inspection	Last performed	Next due
60 MONTH	April 2021	August 2025
120 MONTH	April 2021	August 2030
240 MONTH	April 2021	September 2030

2000 BOMBARDIER GLOBAL EXPRESS S/N 9023

INTERIOR

	Description
NUMBER OF PASSENGERS	Twelve (12)
GALLEY LOCATION	Forward
FORWARD CABIN CONFIGURATION	Four (4) Place Double Club
MID CABIN CONFIGURATION	Two (2) Place Club Opposite Four (4) Place Conference Group
AFT CABIN CONFIGURATION	Two (2) Place Club Opposite Three (3) Place 9G Divan
LAVATORY LOCATION(S)	Forward Crew and Aft Executive
CREW REST	Yes
JUMPSEAT	Yes
LAST REFURBISHED DATE	Refurbished by Bombardier in September 2015


EXTERIOR

BASE PAINT COLOR(S)	Matterhorn White
SECONDARY COLOR(S)	Mercedes Brown
LAST PAINTED DATE	Painted by Bombardier in September 2015



CONNECTIVITY

HIGH SPEED INTERNET	SwiftBroadband WiFi
---------------------	---------------------



2000 BOMBARDIER GLOBAL EXPRESS S/N 9023



2000 BOMBARDIER GLOBAL EXPRESS S/N 9023



2000 BOMBARDIER GLOBAL EXPRESS S/N 9023



