



2,288
Hours

901 Landings



# Highlights

- Engines Enrolled on MSP Gold
- APU Enrolled on MSP Gold
- FANS 1/A
- SwiftBroadband



### Airframe

TOTAL TIME SINCE NEW	2,288 Hours (as of October 31, 2022)
TOTAL LANDINGS SINCE NEW	901 Landings
IN-SERVICE DATE	March 2014
MAINTENANCE TRACKING	CAMP

Engines	Left	Center	Right
DESCRIPTION	Honeywell TFE731-	60-1C	
SERIAL NUMBER(S)	134119	134120	134121
TOTAL HOURS SINCE NEW	2,263 Hours	2,288 Hours	2,228 Hours
TOTAL CYCLES SINCE NEW	888 Cycles	901 Cycles	877 Cycles
PROGRAM COVERAGE	Honeywell MSP Gol	d	

#### APU

DESCRIPTION	Honeywell GTCP 36-150
SERIAL NUMBER	P-631
APU TOTAL TIME SINCE NEW	1,677 Hours
PROGRAM COVERAGE	Honeywell MSP Gold

# Connectivity

HIGH SPEED INTERNET	SwiftBroadband
IN-FLIGHT PHONE	Aircell Axxess II

## Entertainment

DISPLAY / MONITOR(S)	Forward and Aft Bulkhead Monitors Galley Control Monitor
CABIN MANAGEMENT SYSTEM	Collins Falcon Cabin HD





#### **Avionics**

Type of unit	Qty	Description
EFIS (ELECTRONIC FLIGHT INSTRUMENT SYSTEM)	4 LCD	Honeywell DU-1310
FMS (FLIGHT MANAGEMENT SYSTEM	Triple	Honeywell
IRS (INERTIAL REFERENCE SYSTEM)	Triple	Honeywell LASERF V
GPS (GLOBAL POSITIONING SYSTEM)	Dual	Honeywell
ADC (AIR DATA COMPUTER)	Dual	Honeywell AZ-200
NAV (NAVIGATION RADIO)	Dual	Honeywell NV-875B
DME (DISTANCE MEASURING EQUIPMENT)	Dual	Honeywell DM-855
ADF (AUTOMATIC DIRECTION FINDER)	Dual	Honeywell DF-855
VHF COM (Very High Freq. Communications)	Triple	Honeywell TR-866B
HF COM (HIGH FREQ. COMMUNICATIONS)	Dual	Collins HF-9034A
SATCOM (SATELLITE COMMUNICATIONS)	Single	Honeywell MCS-7120
WRADAR (WEATHER RADAR)	Single	Honeywell WU-880
RADAR ALT (RADAR ALTIMETER)	Single	Honeywell RT-300
XPNDR (TRANSPONDER)	Dual	Honeywell XS-857A
GPWS (GROUND PROXIMITY WARNING SYSTEM)	Single	Honeywell EGPWM

Type of unit	Qty	Description
TCAS (TRAFFIC COLLISION AVOIDANCE SYSTEM)	Single	ACSS TCAS 3000
CVR (COCKPIT VOICE RECORDER)	Single	Honeywell SSCVR
FDR (FLIGHT DATA RECORDER)	Single	Honeywell SSFDR
LSS (LIGHTNING SENSOR SYSTEM)	Single	Honeywell LSS-860
ELT (EMERGENCY LOCATOR TRANSMITTER)	Single	ADT 406

## Noteable avionics compliance

EASy II Baseline
SBAS LPV
Honeywell EASy II Automatic Dependent Surveillance - Broadcast Out (ADS-B Out)
Honeywell EASy II CPDLC   ATN
Honeywell EASy II CPDLC   FANS 1/A

FalconPerf + Electronic Jeppesen Charts





### Interior

NUMBER OF PASSENGERS	Fourteen (14)
GALLEY LOCATION	Forward
FORWARD CABIN CONFIGURATION	Four (4) Place Club
MID CABIN CONFIGURATION	Four (4) Place Conference Group opposite Credenza
AFT CABIN CONFIGURATION	Three (3) Place Divan opposite Three (3) Place Divan
LAVATORY LOCATION(S)	Forward Crew & Aft Executive
GALLEY EQUIPMENT	High Temp Oven and Espresso Maker
REFURBISHMENT	New Carpet February 2020


### Exterior

BASE PAINT COLOR(S)	Ice Gray and Stardust
STRIPE COLOR(S)	Violet and Pearl Fawn
REFURBISHMENT	February 2020 at Duncan Aviation, Battle Creek

# Major inspection status

Inspection	Last Performed	Next Due
12 Month	February 2022	February 2023
24 Month	February 2022	February 2024
36 Month	February 2020	February 2023
1C / 72 Month	February 2020	February 2026
2C / 144 Month	-	March 2026

# Floorplan





















#### Dassault Falcon 900LX S/N 274









registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.

Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos,

#### Dassault Falcon 900LX S/N 274

















































#### FOR YOUR WORLD