



5,449
Hours

5,184 Landings



Highlights

- Engines Enrolled on MSP
- APU Enrolled on MSP
- Flight Data Recorder (88 Parameters)
- Pro Line 21
- Fresh 48 Month Inspection
- 8 + 1 Passenger Configuration
- No Damage History

Airframe

TOTAL TIME SINCE NEW	5,449 Hours
TOTAL LANDINGS SINCE NEW	5,184 Landings
ENTRY INTO SERVICE DATE	September 2005

Engines	Left	Right
DESCRIPTION	Honeywell TFE731-5	BBR
TOTAL HOURS SINCE NEW	7,842 Hours	7,842 Hours
TOTAL CYCLES SINCE NEW	4,546 Cycles	5,474 Cycles
PROGRAM COVERAGE	MSP	

Avionics

The Beechcraft Hawker 800XP is equipped with an integrated, Rockwell Collins Pro Line 21 avionics suite.

APU

DESCRIPTION	Honeywell 36-150
APU TOTAL TIME SINCE NEW	5,265 Hours
PROGRAM COVERAGE	MSP

Notable features

Belted Lavatory	Flight Data Recorder (88 Parameters)
Dual FMS	ADS-B
Pro Line 21	RVSM



Interior

NUMBER OF PASSENGERS	Eight (8) + One (1)
GALLEY LOCATION	Forward
FORWARD CABIN CONFIGURATION	Four (4) Place Club
AFT CABIN CONFIGURATION	Three (3) Place Divan opposite One (1) Single Seat
LAVATORY LOCATION	Aft (Belted Lav)
JUMPSEAT	Yes
LAST REFURBISHED DATE	April 2021


Exterior

BASE PAINT COLOR	Matterhorn White
STRIPE COLORS	Dark Blue & Light Blue
LAST PAINTED DATE	2015

Major inspection status

Inspection	Last Performed	Next Due
24 Month	January 2024	January 2026
48 Month	June 2025	June 2029
Landing Gear Overhaul	May 2017	May 2029 / 8,275 Cycles

Floorplan



2005 Beechcraft Hawker 800XP S/N 258722















2005 Beechcraft Hawker 800XP S/N 258722







FOR YOUR WORLD